

VEHICLE INSPECTION REPORT

DG680FN

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 07/09/2018

Year 2018

Mileage 132,212 Miles
Warranted

Fuel Type DIESEL

Colour WHITE

VIN WDB9061332N732907

Body Style Dropside MWB

MOT Due 06/09/2025

CAP Clean £5,300.00

CAP Average £4,550.00

CAP Below £3,550.00

Gearbox MANUAL

Tail Lift Column

BROKEN DPF

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
UpTo 25mm Thru Paint



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Wing nsf
Dented
2 Or Less UpTo 10mm



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Dented
With Paint Damage



6: Door nsf
Dented
With Paint Damage



7: Door nsf
Dented
Over 30mm



8: Door nsf
Chipped
Multiple Chips



9: B Post ns
Chipped
Multiple Chips



10: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm



11: Other
N/A
N/A



12: Other
N/A
N/A



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



14: Door Moulding osf
Scuffed (Unpainted)
UpTo 100mm



15: Sill os
Scratched
Over 25mm Thru Paint



16: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	