

# VEHICLE INSPECTION REPORT

**C397413**

## SDC DROPSIDE

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |                         |            |                   |                 |      |
|-----------|-------------------------|------------|-------------------|-----------------|------|
| Reg. date | 01/01/2015              | Colour     | BLUE              | Brakes          | Disc |
| Year      | 2015                    | VIN        | SDCPL42D300135847 | Axle Combi      | Tri  |
| Mileage   | 1,224 Hours Not Showing | Body Style | Trailer           | Rear Suspension | Air  |
| Fuel Type |                         | MOT Due    | 31/05/2026        |                 |      |

MERCEDES AXLES, FRONT LIFT, REAR STEAR, HIAB XS099 HIPRO GRAB ON RAILS, RAISE AND LOWER VALVE, FERRY LASHING RINGS

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos





